

# Mittagong Sands Pty Ltd

Jan-26

Mittagong Quarry - Wombeyan Caves Road, Mittagong NSW 2575

EPA Licence No: 3132

## Monitoring Requirements:

Grab samples are required to be taken within the first 2 hours following each 5-day consecutive rainfall event and tested for pH, total suspended solids and turbidity.

## Location of Monitoring Points:

Monitoring Point 1: Steel pipe and overflow channel discharge from sediment pond labelled "SFSW-1" on map titled "Figure 5.3 Environmental Monitoring" submitted to the EPA with Licence Information Form dated 11/11/99.

## Summary of Results:

### Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
pH	pH	5.5 - 8.5	6	6	6
Total Suspended Solids	mg/L	50	28	28	28
Turbidity	NTU	20	9	9	9

## Individual Results:

### Monitoring Point 1:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
21/01/2026	pH	pH	5.5 - 8.5	5.9	N
	TSS	mg/L	50	28	N
	Turbidity	NTU	20	9	N

# Mittagong Sands Pty Ltd

Feb-26

Mittagong Quarry - Wombeyan Caves Road, Mittagong NSW 2575

EPA Licence No: 3132

## Monitoring Requirements:

Grab samples are required to be taken within the first 2 hours following each 5-day consecutive rainfall event and tested for pH, total suspended solids and turbidity.

## Location of Monitoring Points:

Monitoring Point 1: Steel pipe and overflow channel discharge from sediment pond labelled "SFSW-1" on map titled "Figure 5.3 Environmental Monitoring" submitted to the EPA with Licence Information Form dated 11/11/99.

## Summary of Results:

### Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
pH	pH	5.5 - 8.5			
Total Suspended Solids	mg/L	50			
Turbidity	NTU	20			

## Individual Results:

### Monitoring Point 1:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
<i>No discharge events during this period</i>					

# Mittagong Sands Pty Ltd

Mar-26

Mittagong Quarry - Wombeyan Caves Road, Mittagong NSW 2575

EPA Licence No: 3132

## Monitoring Requirements:

Grab samples are required to be taken within the first 2 hours following each 5-day consecutive rainfall event and tested for pH, total suspended solids and turbidity.

## Location of Monitoring Points:

Monitoring Point 1: Steel pipe and overflow channel discharge from sediment pond labelled "SFSW-1" on map titled "Figure 5.3 Environmental Monitoring" submitted to the EPA with Licence Information Form dated 11/11/99.

## Summary of Results:

### Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
pH	pH	5.5 - 8.5	6	6	6
Total Suspended Solids	mg/L	50	<10	<10	<10
Turbidity	NTU	20	8	8	8

## Individual Results:

### Monitoring Point 1:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
9/03/2026	pH	pH	5.5 - 8.5	6.01	N
	TSS	mg/L	50	<10	N
	Turbidity	NTU	20	8.37	N

# Mittagong Sands Pty Ltd

Apr-26

Mittagong Quarry - Wombeyan Caves Road, Mittagong NSW 2575

EPA Licence No: 3132

## Monitoring Requirements:

Grab samples are required to be taken within the first 2 hours following each 5-day consecutive rainfall event and tested for pH, total suspended solids and turbidity.

## Location of Monitoring Points:

Monitoring Point 1: Steel pipe and overflow channel discharge from sediment pond labelled "SFSW-1" on map titled "Figure 5.3 Environmental Monitoring" submitted to the EPA with Licence Information Form dated 11/11/99.

## Summary of Results:

### Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
pH	pH	5.5 - 8.5			
Total Suspended Solids	mg/L	50			
Turbidity	NTU	20			

## Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
<i>No discharge events during this period</i>					

### Monitoring Point 1: