Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	рН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

|--|

Monitoring Point 1:

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	pН	6.5 - 8.5	-	-	-
Total Suspended Solids	ma/L	50	-	-	-

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)

Monitoring Point 1:

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	рН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)

Monitoring Point 1:

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	рН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)

Monitoring Point 1:

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	рН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)

Monitoring Point 1:

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	рН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)			
No discharge events during period								

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	рН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)		
No discharge events during period							

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	pН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)		
No discharge events during period							

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	pН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)		
No discharge events during period							

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	рН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

	Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
--	-------------	-----------	--------------------	---------------------------------------	-------------	---------------------

Monitoring Point 1:

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	pН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)		
No discharge events during period							

Newcastle - 1A McIntosh Drive, Mayfield West NSW 2304

EPA Licence No: 20771

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge event.

Location of Monitoring Points:

Monitoring Point 1: Valve controlled outlet chamber and pipeline located within sedimentation pond in north-western corner of the site (see

Figure 2.1 in DOC15/0291).

Summary of Results:

Monitoring Point 1:

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
Oil and Grease	mg/L	10	-	-	-
рН	рН	6.5 - 8.5	-	-	-
Total Suspended Solids	mg/L	50	-	-	-

Individual Results:

Mon	itorina	Point	1

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)		
No discharge events during period							