Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *	
Airblast Overpressure	dB (Lin Peak)	120	115	
Ground Vibration Level	mm/s	10	5	

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

	Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
No Blasting Conducted During This Period					

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter	Parameter Unit of Measure		Allowable Exceedance *	
Airblast Overpressure	dB (Lin Peak)	120	115	
Ground Vibration Level	mm/s	10	5	

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

	Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
No Blasting Conducted During This Period					

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

	Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
No Blasting Conducted During This Period					

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter Unit of Measure		Criteria (at any time)	Allowable Exceedance *	
Airblast Overpressure	dB (Lin Peak)	120	115	
Ground Vibration Level	mm/s	10	5	

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

	Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
No Blasting Conducted During This Period					

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter	Parameter Unit of Measure		Allowable Exceedance *	
Airblast Overpressure	dB (Lin Peak)	120	115	
Ground Vibration Level	mm/s	10	5	

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

	Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
No Blasting Conducted During This Period					

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter Unit of Measure		Criteria (at any time)	Allowable Exceedance *	
Airblast Overpressure	dB (Lin Peak)	120	115	
Ground Vibration Level	mm/s	10	5	

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

	Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
No Blasting Conducted During This Period					

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
03/07/2018 13:58:00 PM	Airblast	dB (Lin Peak)	101.0	N
03/01/2010 13.30.00 FW	Ground Vibration	mm/s	1.800	N

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *	
Airblast Overpressure	dB (Lin Peak)	120	115	
Ground Vibration Level	mm/s	10	5	

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
No Blasting Conducted During This Period				

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *	
Airblast Overpressure	dB (Lin Peak)	120	115	
Ground Vibration Level	mm/s	10	5	

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
No Blasting Conducted During This Period				

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *	
Airblast Overpressure	dB (Lin Peak)	120	115	
Ground Vibration Level	mm/s	10	5	

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
No Blasting Conducted During This Period				

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *	
Airblast Overpressure	dB (Lin Peak)	120	115	
Ground Vibration Level	mm/s	10	5	

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
No Blasting Conducted During This Period				

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Summary of Results:

Monitoring Point 1:

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *	
Airblast Overpressure	dB (Lin Peak)	120	115	
Ground Vibration Level	mm/s	10	5	

^{*} applies to 95% of total number of blasts conducte during each reporting period.

Individual Results:

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
03/12/2018 15:10:00 PM	Airblast	dB (Lin Peak)	102.8	N
03/12/2016 13.10.00 FW	Ground Vibration	mm/s	1.780	N