

**Benedict Industries Pty Ltd**

Jan-26

**Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171****EPA Licence No: 1924****Blast Monitoring Requirements:**

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

**Location of Monitoring Points:**

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Monitoring Point 2: any point within 20 metres of 13 Carinya Road, Picnic Point NSW 2213.

**Summary of Results:****Monitoring Point 1:**

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

\* applies to 95% of total number of blasts conducted during each reporting period.

**Individual Results:****Monitoring Point 1:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
<i>No Blasting conducted during this period</i>				

**Monitoring Point 2:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
<i>No Blasting conducted during this period</i>				

**Benedict Industries Pty Ltd**

Feb-26

**Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171****EPA Licence No: 1924****Blast Monitoring Requirements:**

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

**Location of Monitoring Points:**

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Monitoring Point 2: any point within 20 metres of 13 Carinya Road, Picnic Point NSW 2213.

**Summary of Results:****Monitoring Point 1:**

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

\* applies to 95% of total number of blasts conducted during each reporting period.

**Individual Results:****Monitoring Point 1:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
11/02/2026 13:59	Airblast Overpressure	dB (Lin Peak)	0*	N
	Ground Vibration Level	mm/s	0*	N

**Monitoring Point 2:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
11/02/2026 13:59	Airblast Overpressure	dB (Lin Peak)	101.9	N
	Ground Vibration Level	mm/s	1.397	N

\* Did not trigger

**Benedict Industries Pty Ltd**

Mar-26

**Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171****EPA Licence No: 1924****Blast Monitoring Requirements:**

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

**Location of Monitoring Points:**

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Monitoring Point 2: any point within 20 metres of 13 Carinya Road, Picnic Point NSW 2213.

**Summary of Results:****Monitoring Point 1:**

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

\* applies to 95% of total number of blasts conducted during each reporting period.

**Individual Results:****Monitoring Point 1:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
24/03/2026 13:34	Airblast Overpressure	dB (Lin Peak)	0*	N
	Ground Vibration Level	mm/s	0*	N

**Monitoring Point 2:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
24/03/2026 13:34	Airblast Overpressure	dB (Lin Peak)	108.0	N
	Ground Vibration Level	mm/s	0.38	N

\* Did not trigger

**Benedict Industries Pty Ltd**

Apr-26

**Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171****EPA Licence No: 1924****Blast Monitoring Requirements:**

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

**Location of Monitoring Points:**

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Monitoring Point 2: any point within 20 metres of 13 Carinya Road, Picnic Point NSW 2213.

**Summary of Results:****Monitoring Point 1:**

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

\* applies to 95% of total number of blasts conducted during each reporting period.

**Individual Results:****Monitoring Point 1:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
<i>No Blasting conducted during this period</i>				

**Monitoring Point 2:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
<i>No Blasting conducted during this period</i>				

**Benedict Industries Pty Ltd**

May-26

**Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171****EPA Licence No: 1924****Blast Monitoring Requirements:**

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

**Location of Monitoring Points:**

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Monitoring Point 2: any point within 20 metres of 13 Carinya Road, Picnic Point NSW 2213.

**Summary of Results:****Monitoring Point 1:**

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

\* applies to 95% of total number of blasts conducted during each reporting period.

**Individual Results:****Monitoring Point 1:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
<i>No Blasting conducted during this period</i>				

**Monitoring Point 2:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
<i>No Blasting conducted during this period</i>				

**Benedict Industries Pty Ltd**

Jun-26

**Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171****EPA Licence No: 1924****Blast Monitoring Requirements:**

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

**Location of Monitoring Points:**

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Monitoring Point 2: any point within 20 metres of 13 Carinya Road, Picnic Point NSW 2213.

**Summary of Results:****Monitoring Point 1:**

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

\* applies to 95% of total number of blasts conducted during each reporting period.

**Individual Results:****Monitoring Point 1:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
02/06/2026 13:32 PM	Airblast Overpressure	dB (Lin Peak)	0*	N
	Ground Vibration Level	mm/s	0*	N

**Monitoring Point 2:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
02/06/2026 13:32 PM	Airblast Overpressure	dB (Lin Peak)	98.8	N
	Ground Vibration Level	mm/s	1.40	N