

Benedict Industries Pty Ltd

Jan-26

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Blast Monitoring Requirements:

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Monitoring Point 2: any point within 20 metres of 13 Carinya Road, Picnic Point NSW 2213.

Summary of Results:

Monitoring Point 1:

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

* applies to 95% of total number of blasts conducted during each reporting period.

Individual Results:

Monitoring Point 1:

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
<i>No Blasting conducted during this period</i>				

Monitoring Point 2:

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
<i>No Blasting conducted during this period</i>				

Benedict Industries Pty Ltd

Feb-26

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171**EPA Licence No: 1924****Blast Monitoring Requirements:**

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Monitoring Point 2: any point within 20 metres of 13 Carinya Road, Picnic Point NSW 2213.

Summary of Results:**Monitoring Point 1:**

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

* applies to 95% of total number of blasts conducted during each reporting period.

Individual Results:**Monitoring Point 1:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
11/02/2026 13:59	Airblast Overpressure	dB (Lin Peak)	0*	N
	Ground Vibration Level	mm/s	0*	N

Monitoring Point 2:

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
11/02/2026 13:59	Airblast Overpressure	dB (Lin Peak)	101.9	N
	Ground Vibration Level	mm/s	1.397	N

* Did not trigger

Benedict Industries Pty Ltd

Mar-26

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171**EPA Licence No: 1924****Blast Monitoring Requirements:**

At any residence or noise sensitive location (such as school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative airblast overpressure or ground vibration level.

Location of Monitoring Points:

Monitoring Point 1: Sandy Point Community Hall, St George Crescent, Sandy Point NSW 2172.

Monitoring Point 2: any point within 20 metres of 13 Carinya Road, Picnic Point NSW 2213.

Summary of Results:**Monitoring Point 1:**

Parameter	Unit of Measure	Criteria (at any time)	Allowable Exceedance *
Airblast Overpressure	dB (Lin Peak)	120	115
Ground Vibration Level	mm/s	10	5

* applies to 95% of total number of blasts conducted during each reporting period.

Individual Results:**Monitoring Point 1:**

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
24/03/2026 13:34	Airblast Overpressure	dB (Lin Peak)	0*	N
	Ground Vibration Level	mm/s	0*	N

Monitoring Point 2:

Blast Date	Parameter	Unit of Measure	Blast Monitor Result	Exceedance (Y/N)
24/03/2026 13:34	Airblast Overpressure	dB (Lin Peak)	108.0	N
	Ground Vibration Level	mm/s	0.38	N

* Did not trigger