

Benedict Industries Pty Ltd

Jan-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:

Monitoring Point 1:

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:

Monitoring Point 1:

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Benedict Industries Pty Ltd

Feb-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:

Monitoring Point 1:

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:

Monitoring Point 1:

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Benedict Industries Pty Ltd

Mar-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:

Monitoring Point 1:

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:

Monitoring Point 1:

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Benedict Industries Pty Ltd

Apr-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:

Monitoring Point 1:

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:

Monitoring Point 1:

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Benedict Industries Pty Ltd

May-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171**EPA Licence No: 1924****Monitoring Requirements:**

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:**Monitoring Point 1:**

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:**Monitoring Point 1:**

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Benedict Industries Pty Ltd

Jun-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:

Monitoring Point 1:

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:

Monitoring Point 1:

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Benedict Industries Pty Ltd

Jul-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:

Monitoring Point 1:

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Monitoring Point 1:

Benedict Industries Pty Ltd

Aug-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:

Monitoring Point 1:

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:

Monitoring Point 1:

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Benedict Industries Pty Ltd

Sep-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:

Monitoring Point 1:

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:

Monitoring Point 1:

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Benedict Industries Pty Ltd

Oct-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171**EPA Licence No: 1924****Monitoring Requirements:**

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:**Monitoring Point 1:**

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Monitoring Point 1:

Benedict Industries Pty Ltd

Nov-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171**EPA Licence No: 1924****Monitoring Requirements:**

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:**Monitoring Point 1:**

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |

Monitoring Point 1:

Benedict Industries Pty Ltd

Dec-18

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171**EPA Licence No: 1924****Monitoring Requirements:**

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:**Monitoring Point 1:**

| Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Lowest sample value | Highest sample value | Mean of samples |
|------------------------|-----------------|------------------------------------|---------------------|----------------------|-----------------|
| pH | pH | 6 - 8.5 | - | - | - |
| Total Suspended Solids | mg/L | 50 | - | - | - |
| Turbidity | NTU | 50 | - | - | - |

Individual Results:**Monitoring Point 1:**

| Sample Date | Pollutant | Unit of Measure | 100 Percentile Concentration Limit | Test Result | Exceedance (Y/N) |
|--|-----------|-----------------|------------------------------------|-------------|------------------|
| <i>No discharge events during period</i> | | | | | |