

Benedict Industries Pty Ltd

Jan-24

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:**Monitoring Point 1:**

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
pH	pH	6 - 8.5	0.0	0.0	#DIV/0!
Total Suspended Solids	mg/L	50	0.0	0.0	#DIV/0!
Turbidity	NTU	50	0.0	0.0	#DIV/0!

Individual Results:**Monitoring Point 1:**

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
<i>No discharge events during period</i>					

Benedict Industries Pty Ltd

Feb-24

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:**Monitoring Point 1:**

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
pH	pH	6 - 8.5			
Total Suspended Solids	mg/L	50			
Turbidity	NTU	50			

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
<i>No discharge events during period</i>					

Benedict Industries Pty Ltd

Mar-24

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

Water Monitoring Requirements:

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

Location of Monitoring Points:

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

Summary of Results:**Monitoring Point 1:**

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
pH	pH	6 - 8.5			
Total Suspended Solids	mg/L	50			
Turbidity	NTU	50			

Individual Results:

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
<i>No discharge events during period</i>					