

**Benedict Industries Pty Ltd**

Jan-26

**Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171****EPA Licence No: 1924****Water Monitoring Requirements:**

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

**Location of Monitoring Points:**

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

**Summary of Results:****Monitoring Point 1:**

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
pH	pH	5.5 - 8.5	0.00	0.00	0.00
Total Suspended Solids	mg/L	50	0	0	0
Turbidity	NTU	50	0	0	0

**Individual Results:****Monitoring Point 1:**

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
<i>No discharge events during period</i>					

**Benedict Industries Pty Ltd**

Feb-26

Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171

EPA Licence No: 1924

**Water Monitoring Requirements:**

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

**Location of Monitoring Points:**

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

**Summary of Results:****Monitoring Point 1:**

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
pH	pH	5.5 - 8.5	0.00	0.00	0.00
Total Suspended Solids	mg/L	50	0	0	0
Turbidity	NTU	50	0	0	0

**Individual Results:**

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
<i>No discharge events during period</i>					

**Benedict Industries Pty Ltd**

Mar-26

**Sandy Point Quarry - Heathcote Road, Sandy Point NSW 2171****EPA Licence No: 1924****Water Monitoring Requirements:**

Grab samples are required to be taken daily during any discharge and tested for pH, total suspended solids and turbidity.

**Location of Monitoring Points:**

Monitoring Point 1: Below Basin 3 as identified in map attached to the "Sandy Point Quarry Sediment Controls and Protocols Update December 2013."

**Summary of Results:****Monitoring Point 1:**

Pollutant	Unit of Measure	100 Percentile Concentration Limit	Lowest sample value	Highest sample value	Mean of samples
pH	pH	5.5 - 8.5	0.00	0.00	0.00
Total Suspended Solids	mg/L	50	0	0	0
Turbidity	NTU	50	0	0	0

**Individual Results:**

Sample Date	Pollutant	Unit of Measure	100 Percentile Concentration Limit	Test Result	Exceedance (Y/N)
<i>No discharge events during period</i>					